

FOLLOW APPLICATION INSTRUCTIONS
NOTICE
FOLLOW APPLICATION INSTRUCTIONS



GLITTER

APPLICATION INSTRUCTIONS

Firm Pressure

375-380 degrees F

- 1. Pre-heat garment 2 seconds.**
- 2. Apply transfer 14 seconds.**
- 3. Cool completely and gently peel.**