

FOLLOW APPLICATION INSTRUCTIONS

NOTICE

FOLLOW APPLICATION INSTRUCTIONS



P.C. Patterns

APPLICATION INSTRUCTIONS

Medium Pressure

330 degrees F

- 1. Pre-heat garment 5 seconds.**
- 2. Apply for 15 seconds.**
- 3. Peel cold.**