

FOLLOW APPLICATION INSTRUCTIONS
NOTICE
FOLLOW APPLICATION INSTRUCTIONS



PC SHIMMER

PRECISION CUT APPLICATION INSTRUCTIONS

Light Pressure

320 degrees F

- 1. Pre-heat garment 4 seconds.**
- 2. Apply precision cut 14 seconds.**
- 3. Cool completely and peel.**