

FOLLOW APPLICATION INSTRUCTIONS  
**NOTICE**  
FOLLOW APPLICATION INSTRUCTIONS



# ULTRA STRETCH

**\*NEW APPLICATION INSTRUCTIONS**

Medium Pressure

**330-335 degrees F**

1. Pre-heat garment 2 seconds.
2. Apply transfer 12-14 seconds.
3. Peel COLD!